




Signalling Shared Learning Engineering Services Deliver



Issue 02 - December 2023

Putting passengers first

Introduction

This Signalling Shared Learning details various events and incidents that have occurred on Signalling Projects between July 2023 and December 2023, and provides the key learning points associated with them.

It is intended for distribution within the Network Rail Signalling community and the wider Supply Chain in order to raise awareness of the learning points within, and to enable best practice to be applied throughout all of our signalling activities.

35th anniversary of the Clapham Disaster

Background

December 2023 marks the 35th anniversary of the Clapham Rail Disaster, where 35 passengers and train crew lost their lives. 484 were injured.

The disaster was caused by a single, loose and uninsulated stray wire.

This resulted in a relay energising, allowing a signal to display a green aspect when it should have been red. The result was a rear end collision between two trains, with a third train on the adjacent line colliding with the subsequent wreckage.

Key Learning

We must remember these historic incidents and the key learning associated with them. Many of our industry's rules, procedures, standards and practices of today are as a direct result of previous incidents and the learning from them, so a repeat can be avoided.

There is a real risk of “corporate memory loss”, of this and other accidents and the collective forgetting of what we must do, and why we do it.



SMTH crossed wires

Background

After a track renewal project, previously disconnected signal and track circuit cables were reconnected and tested using the Signal Maintenance Testing Handbook (SMTH).

One of the first trains the following morning reported receiving a red aspect following green aspects, where a yellow was expected. This train SPADed the red signal and came to a stand.

A 2nd following train then received a yellow aspect instead of the red expected, and narrowly avoided a rear end collision with the first train, only because of the actions of the train driver and the signaller.

Key Learning

This incident is one of several SMTH irregularities recently experienced. All staff, particularly SMTH testers, are reminded of the importance of carrying out SMTH fully and correctly, and of the independence required between installation and test.

Non-technical skills training is available, including a module on conscientiousness.



TPWS Intervention

Background

A train driver report a TPWS activation on approach to a buffer stop, set at 10mph. Following local S&T Technician investigation, the TPWS loops were found to be 5.5m apart, rather than the 4.5m shown on the signalling plan. Following loop replacement at 4.5m as per the drawings, two further trains also reported TPWS activations.

Unbeknownst to the technicians, in response to several historic 'reset and go' and unwarranted TPWS interventions, in 2006 a 'TPWS Optimisation Project' undertook analysis and stakeholder consultation that led to the use of 5.5m spacing for Buffer Stop TPWS; this change applied to all new installations and was also applied to all existing installations. To aid efficient delivery of this campaign change, a slimmed down process was adopted that **did not** include updating of records and plans that had already been returned to NRG following the initial fitments.

Key Learning

Projects should be aware of this potential for drawing deficiency, and are reminded that other drawing discrepancies and correlation errors may also be present in records and drawings, particularly where standards have changed since the original equipment was installed.

A Notice Board is forthcoming to further publicise this issue.

This incident is also a further example of "corporate memory loss" and the potential consequences of this.

7 Design of TPWS at buffer stops

The trigger loop shall be placed a minimum of 55 metres before the buffer stop.

The OSS set speed will normally be 12.5 mph (separation of 5.5m).

The trigger loop may be placed up to 67m from the buffer stop with no change in separation.

For trigger loop distances in excess of 67m the following separations and set speeds shall be used:-

- a) Up to 72m, separation of 6m (set speed of 13.5mph),
- b) Up to 77m, separation of 6.5m (set speed of 14.5mph).

Page 12 of 24

Ref:	T1022 appendix A
Issue:	4
Date:	7 th April 2019
Compliance date:	7 th April 2019

The buffer stop OSS is intended to minimise the consequences of a buffer stop collision for an approaching train speed up to 20 mph.

Ref:	RT/E/S/10138
Issue:	3
Date:	April 2004

Due to an interaction between the transmitted field and the trainborne receiving equipment seen at slow speed, a specific Buffer Stop Mini-Loop is used as Buffer Stop OSS equipment. The Buffer Stop Mini-Loops require accurate setting up to avoid unwarranted brake applications at slow speeds as defined in section 10.3.

The Buffer Stop Mini-Loop has a maximum operating speed of 50mph.

10.2 Transmitter loop positioning rules

The leading edge of the OSS Trigger Loop shall normally be positioned 55 metres (+/- 2 metres) on the approach to the effective face of the Buffer Stop with a separation distance (S) of 4.5 metres to the leading edge of the Arming Loop. This equates to a Set Speed of 10 mph, the minimum possible using Buffer Stop Mini-Loops.

Where it is not possible to position the leading edge of the Transmitter Loop at this nominal position, then the Trigger Loop shall be positioned further on the approach to the Buffer Stop with the appropriate separation distance (S) and Set Speed as defined in Table 10. Table 10 also defines the Trigger and Arming loop separation distance (S) and corresponding Set Speed for this range.

Distance Buffer Stop to Trigger Loop (metres)	Separation Distance (S) Trigger Loop to Arming Loop (metres)	Set Speed (mph)
58 - 62	5.0	11.5
63 - 67	5.5	12.5
68 - 72	6.0	13.5
73 - 77	6.5	14.5

Table 10 – Distance between OSS Trigger and Arming Loops and Corresponding Set Speeds – Buffer Stops

Cable ties on gantry



Key Learning

NR/SP/SIG/19812 Cross Track Cable Management and NR/BS/LI/424 state:

- “New cabling shall not be attached to...
d) a cable tray or containment system using cable ties or fixings that are susceptible to degradation from heat, moisture and ultraviolet radiation within the design life of the system.”

Projects are reminded they are to install cables on gantries and other structures in line with this guidance, using an approved method of securement.

Background

Multiple signal cables fell from a signal gantry onto the OHLE below, causing considerable damage to a signalling location case. The cable tray was mounted vertically, conflicting with current standards, but allowed at time of installation.

A similar incident occurred in January 2020, included in Shared Learning SL22.



Insecure cable on gantry



Background

After a period of strong winds, a cable that had been secured to a signal gantry became loose, and arced from the 25kV OHLE causing extensive damage to the signalling apparatus. The equipment had been installed around 5 years previously.

Key Learning

Investigations highlighted standard nylon cables ties had been used to secure the cables to the gantry structure, contrary to NR/SP/SIG/19812 Cross Track Cable Management and NR/BS/LI/424 which states:

“New cabling shall not be attached to...
d) a cable tray or containment system using cable ties or fixings that are susceptible to degradation from heat, moisture and ultraviolet radiation within the design life of the system.”

This is believed to have caused the cables to come free.

Projects should ensure they install cable on gantries and other structures in line with this guidance, using an approved method of securing.

Signaller Reminder on ARS Workstation



Background

An existing SSI interlocking had been altered several times over the previous ten years, as part of various signalling interventions and re-controls. During this period, some non-safety critical functions were implemented in the Control System environment, rather than the interlocking.

The signaller at a ROC workstation reported an occurrence that with Signaller reminder applied on a particular signal, the Automatic Route Setting (ARS) system 'signalled' a train through the signal to the next section.

This signal had been altered as part of previous works to enable ARS.

Data to perform Signaller Reminder applied check on ARS requested routes had been omitted from the system wide application for signals in the interlocking area.

No check of the Signaller Reminder Applied function was performed by the signalling and control system when ARS made the route request.

Key Learning

Close attention should be paid to legacy systems where controls may not be as expected, and where assumptions may cause issues that are not immediately visible.

Over recent years there has been an increase in controls deemed non-safety critical being moved from the interlocking to the control system. As the controls can reside in either system it is important that the location and responsibility is identified, understood and documented. If required, clarification is to be sought from the Infrastructure Manager.

Formalise all decision making, especially where transferring responsibility and seek confirmation of actions being allocated, actioned and closed.

LED Route Indicators- Terminal Allocation

Background

There is no standard convention for the assignment of indication circuit wires to the terminal block in the Miniature and Standard LED Indicator enclosure. Terminals are assigned in the location design; but this may not be issued to the supplier.

A signal was provided with a SARI which initially had four route indications and the design was issued for factory construction. Subsequently, a design modification was issued to modify a Platform 2 route indication to “2D” and “2U”; as the same destination can be approached via two different routes. The route indication arrangements were communicated to the supplier; however, the issued design required to be modified on site to match the route indicator internal wiring.



Key Learning

Projects and designers are asked to adopt the convention that terminals are numbered in the indications in alphanumerical order, i.e.

- Alphabetical (A to Z); then,
- Numerical (0 to 9); then,
- Alphanumerical (A1 to Z9)
- Numeric-alphabetical (1A to 9Z)

Projects must be aware of this hazard and ensure that indications correlate to the wiring at the pre-testing stage, by illuminating the aspects at a suitable and safe time.

Further Information

For any further details or information regarding any of the incidents, please contact:

Chris Ruddy: Senior Engineer – Engineering Services Delivery, Route Services

Tel: 07799 336772

email: christopher.ruddy@networkrail.co.uk

